



**TOWN OF WESTFORD,
MASSACHUSETTS**

**Selective Demolition and
Abatement - 12 North Main
Street**

**EXISTING CONDITIONS OF
12 NORTH MAIN STREET**

March 21, 2016




Westford GIS Map – 12 North Main Street Parcel Highlighted in Yellow




May 2015 Photograph



A (lower level)



Index to Photographs (arrow indicates approximate direction of the photograph)



E (upper level)



B (lower level)



C (lower level)



D (exterior)

Remove collapsed roof debris shown below
(Photograph Facing South)



Remove of collapsed roof and associated debris (view of building facing North)



Photograph taken
January 6, 2016

Remove materials that collapsed through the floor, keeping stabilizing beams intact to support the remaining floor



Photograph taken
January 15, 2016

Remove materials that collapsed through the floor, keeping stabilizing beams intact to support the remaining floor



Photograph taken
January 15, 2016